



Annexure D

BUILDING SAFETY CERTIFICATE

No. 188

Date: 05-02-2025

It is certified that the existing building ....Donyi Polo Vidya Niketan, Ngorlung.... (name of the building of premises at ...Ngorlung, P.D.-Rokshin, District East Siang (A.P.)... (address) is having block(s)/Floor(s) as per detail below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. Of Floor(s) in the Block	01	01				


The building is owned/occupied by ...Donyi Polo Vidya Niketan, Ngorlung..... (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of .....P.W.D..... (name of Department/ Govt.) on ..20-01-2025.. (date of inspection) in the presence of .....Principal..... (name and addresses of the Manager/Secretary of his representative) and that the building/premises is fit for occupancy for running school with effect from .....20-01-2025.. for a period of .....1 (One)..... years in accordance with rule and subject to compliance of the specific conditions as appended.

1. - Good condtn -
2. - Very Good condtn
3. -
4. -

Issued on 05-02-2025 at 10:30 AM by

- Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

  
20/1/2025

Name: Tapu Lata

Designation: AE P.W.D.

Name & Address of Department/Office: Assistant Engineer  
Bilat P.W.D. Sub-Division  
Arunachal Pradesh